

Screws needed to secure the soldering iron tip on the MATCHLESS Soldering Iron (Model 557)

There are two set screws needed to secure the soldering tip into the heater cavity on the MATCHLESS Soldering Iron (Model 557).

The set screws needed to secure the tip have are M5-0.8 x 5mm

HakkoUSA Knowledge Base

<http://kb.hakkousa.com/KnowledgebaseArticle11723.aspx>