What is the temperature accuracy for the thermocouples used by the HAKKO FR-1418 BGA Rework System?

The accuracy of the thermocouples used by the HAKKO FR-1418 BGA Rework System is $\pm 5^{\circ}\text{C}$.

HakkoUSA Knowledge Base

 $\underline{https://kb.hakkousa.com/Knowledgebase/10633/What-is-the-temperature-accurac...}$