All T39 Series Tips meet the minimum temperature accuracy of  $\pm 15^{\circ}C/\pm 27^{\circ}F$  with the exception of the following 4 select tips, which have a minimum temperature accuracy of  $\pm 25^{\circ}C/\pm 45^{\circ}F$  due to their shape and mass:

- T39-DLS15
- T39-SP104
- T39-SP157
- T39-SP212

HakkoUSA Knowledge Base https://kb.hakkousa.com/Knowledgebase/12050/Minimum-Temperature-Accuracy-fo...